

[Back To Article](#)

GLOVEBOX AREA RATTLE

TECHNICAL SERVICE BULLETIN

Reference Number(s): 76/08/99/NAS,Â Date of Issue:Â May 19, 1999

LAND ROVER: Discovery Series II

ISSUE: 2

SECTION: Body

AFFECTED VEHICLES: Discovery Series II (LT) - Up to XA212438

Superceded Bulletin(s): 76/08/99/NAS

SITUATION

NOTE: The information in this TIB supersedes 76/08/99/NAS.

RATTLE NOISE FROM GLOVEBOX AREA

The customer may notice an intermittent rattle from behind the glovebox.

RESOLUTION

DROP THE GLOVEBOX AND SECURE LOOSE CABLE

When a customer has complained of a rattle in the glovebox area, drop the glovebox to the fully down position and investigate for loose cables in the area. Follow the procedure below.

PARTS INFORMATION

Locally sourced

- Cable ties

WARRANTY CLAIMS

WARRANTY CLAIMS INFORMATION

SRO	Description	Time
76.52.89/30	Access cables behind glovebox and secure	0.20 hrs.

FAULT CODE: K

Normal warranty policy and procedures apply.

REPAIR PROCEDURE

POSITION AND SECURE CABLES BEHIND GLOVEBOX

1. Lower the glove box.
2. Release side latches to drop the glovebox completely down for access behind the dash panel.
3. Inspect to determine that the coaxial cable is located behind the HVAC blower mounting bracket and

that it is secured with a cable tie on the left side.

4. If inspection reveals that routing and cable tie are not properly made, remove the two bolts securing the blower-mounting bracket.
5. Locate the cable behind the HVAC blower and install the mounting bracket.
6. Secure the SRS wire and coaxial cable to the blower mounting bracket on left side with a cable tie. See [Fig. 1](#).
7. If slack is apparent in cable cluster on right side, secure with a cable tie.




Fig. 1: Cable Tie Locations