




Posted 08 February 2011 - 08:59 PM

[illegible]

- 1) Side plate positions
- 2) Support 1 position (Central)
- 3) Support 2 position (Central)
- 4) Rear of bolt hole should be counter bored 2mm to allow correct fitment to the engine mount rubber nut



Edited by western, 12 March 2011 - 03:00 PM.
updated diagram added.

Posted 19 February 2011 - 04:07 PM