Land Rover Range Rover (2010)

Sep 17 2022

STATUS	TOTAL ISSUES	HEALTHY SYSTEMS
Very Bad	**17**	**15**

Issues (9)

⚠️ ABS(ABS control module)

Fault code: C1B00	Steering angle sensor
Fault code: U0126	Lost communication with steering angle sensor module
Fault code: U0421	Invalid data received from ride level control module.

⚠️ RCM(Restraints control module)

Fault code: U0415	Invalid data received from ABS control module

⚡ IPC(Instrument cluster control module)

Fault code: B12FE	Fan
Fault code: U0159	Lost communication with parking assist control module.
Fault code: XP060A	XP060A: Generic communication fault code

⚡ BCM(Body control module)

Fault code: B1087   LIN bus A

Fault code: B1B01   Key transponder

❌ RLM(Ride level control module)

Fault code: C1A06   Rear right height sensor

Fault code: C1A36   Exhaust valve

Fault code: U0416   Invalid data received from vehicle dynamics control module.

⚠️ DDM(Driver's door module)

Fault code: B1108   Driver's door central locking motor

⚠️ PDM(Passenger's door module)

Fault code: B1109   Passenger's door central locking motor

Fault code: B1163   Left mirror heater output

⚡ DABM(Digital audio broadcast module)

Fault code: B11A5   Band 3 antenna

❌ TVM(Television module)

Fault code: B1A56   Antenna circuit

Healthy Systems (15)

✅ PCM(Powertrain control module)

✅ TCM(Transmission control module)

✅ ADCM(Adaptive damping control module)

✅ ATCM(All terrain control module)

✅ PBM(Parking brake control module)

✅ SASM(Steering angle sensor module)

✅ TCCM(Transfer case control module)

✅ DSM(Driver's seat module)

✅ HVAC(Heating ventilation and air conditioning control module)

✅ KVM(Keyless vehicle module)

✅ PAM(Parking assist control module)

✅ APIM(Accessory protocol interface module)

✅ CDP(CD player/changer module)

✅ FEM(Front entertainment control module)

✅ TEL(Cellular telephone control module)