

GOV.UK

Vehicle MOT History

BETA This is a new service – your [feedback \(http://www.smartsurvey.co.uk/s/mot-history\)](http://www.smartsurvey.co.uk/s/mot-history) will help us to improve it.

Check the MOT history of a vehicle

Registration number: X554MOF

- Vehicle make LAND ROVER
- Vehicle model DEFENDER 90
- Date first used 11 December 2000
- Fuel type Diesel
- Colour Black

MOT history of this vehicle

- Test date 26 February 2016
- Expiry date 1 March 2017
- Test Result Pass
- Odometer reading 113,143 miles
- MOT test number 3314 1885 2036

- Test date 2 March 2015
- Expiry date 1 March 2016
- Test Result Pass
- Odometer reading 107,575 miles
- MOT test number 9557 9166 5076
- Advisory notice item(s)
 - Steering box has a slight oil leak (2.2.D.2e)
 - Centre Exhaust has a minor leak of exhaust gases (7.1.2)
 - Rear Exhaust has a minor leak of exhaust gases (7.1.2)
 - Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
 - Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
 - Oil leak
 - off side front hub oil seal leaking

- Test date 2 March 2015
- Test Result Fail
- Odometer reading 107,574 miles
- MOT test number 5772 5156 5098

- Reason(s) for failure
 - Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
 - Nearside Headlamp aim too high (1.8)
 - Offside Headlamp aim too high (1.8)
- Advisory notice item(s)
 - Steering box has a slight oil leak (2.2.D.2e)
 - Centre Exhaust has a minor leak of exhaust gases (7.1.2)
 - Rear Exhaust has a minor leak of exhaust gases (7.1.2)
 - Steering system has slight free play detected at steering wheel (2.2.A.1a)
 - Front brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
 - Rear brake disc worn, pitted or scored, but not seriously weakened (3.5.1i)
 - Oil leak
 - off side front hub oil seal leaking

- Test date 28 November 2013
- Test Result Fail
- Odometer reading 107,556 miles
- MOT test number 4289 1263 3389
- Reason(s) for failure
 - Nearside Front Track rod end ball joint has excessive play (2.2.B.1f)
 - Steering box has a significant oil leak (2.2.D.2e)
 - Offside Steering damper damaged and unserviceable (2.2.C.1d)
- Advisory notice item(s)
 - Drag link end ball joint has slight play (2.2.B.1f)

- Test date 30 November 2012
- Expiry date 29 November 2013
- Test Result Pass
- Odometer reading 104,915 miles
- MOT test number 3062 4513 2378

- Test date 27 November 2012
- Test Result Fail
- Odometer reading 104,915 miles
- MOT test number 4276 1203 2494
- Reason(s) for failure
 - Offside Rear Direction indicator not working (1.4.A.2c)
 - Nearside Headlamp aim too low (1.8)
 - Offside Headlamp aim too low (1.8)
 - Offside Windscreen wiper does not clear the windscreen effectively (8.2.2)

- Test date 22 November 2011
- Expiry date 26 November 2012
- Test Result Pass
- Odometer reading 102,885 miles

- MOT test number 5055 2692 1340
- Test date 27 November 2010
- Test Result Fail
- Odometer reading 95,895 miles
- MOT test number 8937 7193 0355
- Reason(s) for failure
 - Nearside Headlamp aim too low (1.8)
 - Offside Headlamp aim too low (1.8)
- Advisory notice item(s)
 - Nearside Front Drag link end ball joint has slight play (2.2.B.1f)
 - Centre Front Drag link end ball joint has slight play (2.2.B.1f)
 - Rear registration plate deteriorated.
- Test date 27 November 2010
- Expiry date 26 November 2011
- Test Result Pass
- Odometer reading 95,895 miles
- MOT test number 9446 6133 0343
- Advisory notice item(s)
 - Nearside Front Drag link end ball joint has slight play (2.2.B.1f)
 - Centre Front Drag link end ball joint has slight play (2.2.B.1f)
 - Rear registration plate deteriorated.
- Test date 15 April 2009
- Expiry date 14 April 2010
- Test Result Pass
- Odometer reading 81,822 miles
- MOT test number 8512 7540 9135
- Test date 15 April 2009
- Test Result Fail
- Odometer reading 81,822 miles
- MOT test number 3543 6560 9144
- Reason(s) for failure
 - Windscreen washer provides insufficient washer liquid (8.2.3)
- Test date 10 June 2008
- Expiry date 9 June 2009
- Test Result Pass
- Odometer reading 75,973 miles
- MOT test number 9545 9256 8175
- Advisory notice item(s)
 - Steering system slightly rough (2.2.D.1)
 - rear number plate deteriorating

steering damper bushes worn

- Test date 28 May 2008
- Test Result Fail
- Odometer reading 75,529 miles
- MOT test number 4634 6914 8137
- Reason(s) for failure
 - Horn not working (1.6.2a)
- Advisory notice item(s)
 - Steering system slightly rough (2.2.D.1)
 - rear number plate deteriorating
 - steering damper bushes worn

- Test date 31 May 2007
- Expiry date 30 May 2008
- Test Result Pass
- Odometer reading 66,221 miles
- MOT test number 8022 5115 7146
- Advisory notice item(s)
 - Front Brake pad(s) wearing thin (3.5.1g)

- Test date 24 January 2006
- Expiry date 23 January 2007
- Test Result Pass
- Odometer reading 53,702 miles
- MOT test number 7723 6452 6060
- Advisory notice item(s)
 - slight play in steering damper off side rubber bush

[Search again \(/\)](#)