

LAUNCH

Shop Name: EFI Tuning Centre

Address: No.572/3,Nawalapitiya
Road,Ulapane.

Telephone: 0776910984

Fax:

Make: LANDROVER

Model:

Year: 1997 - 2006

VIN:

Test Time: 2020-02-17 09:14:01

Diagnostic path: Manually Select >

Freelander > 1997 - 2006 > ABS >

ABS(1998-2000)

Diagnostic Result

Front Left sensor output too low

Front Left sensor electrical failure