


FWD 5 Speed

JATCO JF506E / Mazda 5F31J



2013.1.0

JATCO JF506E / Mazda 5F31J (FWD 5-Speed)

| VEHICLE MODEL | YEARS | ENGINE | TRANS. TYPE | |
|--|-----------------------------|-----------------|--|---|
| Jaguar X-Type | 2002-10 | 2.5 & 3.0 Litre | JF506E | |
| Mazda MPV (Van) | 2002-06 | 3.0 Litre | 5F31J / JF506E / JA5A-EL | |
| Mazda 6 | 2003-05 | 3.0 Litre | 5F31J / JF506E / JA5A-EL | |
| Land Rover Freelander | 2002-05 | 2.5 Litre | JF506E | |
| Rover 75 (Overseas) | 2002-On | 2.5 Litre | JF506E | |
| VW Jetta | 2002-05 | 1.8 & 2.8 Litre | 09A / JF506E | |
| VW GTi | 2002-06 | 1.8 Litre | 09A / JF506E | |
| VW Golf | 2004-06 | 1.8 & 2.8 Litre | 09A / JF506E | |
| ILL. NO. | PART NUMBER | PER CAR | DESCRIPTION | YEARS |
| --- | TMJF506E | | Technical Manual | 2002-On |
| --- | TMJF506EG | | Technical Manual (Update) | 2002-On |
| --- | TMJF506ER | | Technical Manual (Assembly Procedures) | 2002-On |
| MASTER BOX KITS | | | | |
| --- | K9300A-S¹ | | Master Kit (w/o Steel Plates) | Mazda 2002-06 |
| --- | K9300B-S¹ | | Master Kit (w/o Steel Plates) | Volkswagen 2002-06 |
| --- | K9300C-S¹ | | Master Kit (w/o Steel Plates) | Jaguar, Rover, Freelander 2002-On |
| Steel Plate Sub-Kits: | | | | |
| --- | K9300-9 | | Steel Plate Kit | 2002-On |
| ¹ Kits do not include the molded rubber high clutch retainer, please order 93847 separately. | | | | |
| OVERHAUL KITS, GASKET SETS, SEAL KITS AND COMPONENTS | | | | |
| --- | K93900A¹ | | Overhaul Kit | Mazda 2002-06 |
| --- | K93900B¹ | | Overhaul Kit | Volkswagen 2002-06 |
| --- | K93900C¹ | | Overhaul Kit | Jaguar, Rover, Freelander 2002-On |
| --- | K93900-1¹ | | Gasket and Rubber Kit | All 2002-On |
| --- | K93900-3 | | Valve Body Gasket Set | All 2002-On |
| --- | 93172 | 1 | Side Cover Gasket | Duraprene 2002-On |
| METAL CLAD SEALS | | | | |
| 10C | 93526 | 1 | Converter | 2002-On |
| 11B | 93551 | 2 | Axle (Mazda) | 2002-06 |
| 11B | 93551A | 2 | Axle (Freelander) | 2002-05 |
| 11B | 93551B | 2 | Axle (Volkswagen) | 2002-06 |
| 11B | 93551C | 1-2 | Axle (Rover 75 and Jaguar w/2WD/AWD, Left Side) | 2002-On |
| 11B | 93551D | 1 | Right Axle (Rover 75 and Jaguar w/AWD, Right Side) | 2002-On |
| 12D | 85507 | 1 | Manual Lever Seal | 2002-On |
| 12D | 68504 | 1 | Manual Lever Seal | Freelander Lower 2002-On |
| SEALING RINGS | | | | |
| --- | K93901 | 1 | Sealing Ring Kit | 2002-On |
| 13A | 93203P | 2 | Direct Clutch (Plastic) | 2002-On |
| 14C | 93201T | 3 | Input Shaft (Teflon) | 2002-On |
| 15C | 93200P | 2 | Low Clutch Support (Plastic) | 2002-On |

JATCO JF506E / 5F31J / JA5A-EL (FWD 5-Speed)

| ILL. NO. | PART NUMBER | PER CAR | DESCRIPTION | YEARS |
|--|----------------------------|------------|--|---------|
| SEALING RINGS - Cont'd. | | | | |
| 16B/D | 93204T | 6 | Accumulator Piston (Teflon) | 2002-On |
| 17E | 93202T | 3 | High/Reverse Clutch (Teflon) | 2002-On |
| CLUTCH PLATES | | | | |
| 20A | 93308 | 4 | Direct (Countergear) Friction 24T, .068" - 4.026" O.D. | 2002-On |
| 21A | 93309 | 4 | Direct (Countergear) Steel 24T, .079" - 3.380" I.D. | 2002-On |
| 23B | 87321C | 6 | Low/Reverse Friction 32T, .071" - 5.455" O.D. | 2002-On |
| 24B | 93322 | 6 | Low/Reverse Steel 10T, .055" - 5.908" I.D. | 2002-On |
| 26C | 93310 | 3 | 2-4 Brake Friction 32T, .063" - 7.534" O.D. | 2002-On |
| 27C | 93311 | 2 | 2-4 Brake Steel 7T, .118" - 6.663" I.D. | 2002-On |
| 29C | 74304E | 7 | Low (Forward) Friction 30T, .068" - 5.426" O.D. | 2002-On |
| 30C | 93305 | 7 | Low (Forward) Steel 32T, .055" - 4.814" I.D. | 2002-On |
| 33D | 93306 | 2 | Reverse Friction 32T, .060" - 6.141" O.D. | 2002-On |
| 34D | 93307 | 2 | Reverse Steel 36T, .078" - 5.614" I.D. | 2002-On |
| 35D | 93315 | 1 | Reverse Pressure Plate 36T, .163" - 5.614" I.D. | 2002-On |
| 35D | 93315A | 1 | Reverse Pressure Plate 36T, .140" - 5.614" I.D. | 2002-On |
| 36E | 87302D | 5 | High Friction 24T, .063" - 4.416" O.D. | 2002-On |
| 37E | 93303 | 4 | High Steel 18T, .095" - 3.596" I.D. | 2002-On |
| 37E | 93303A | 1 | High Steel 18T, .063" - 3.596" I.D. | 2002-On |
| BANDS | | | | |
| 40A | 93714 | 1 | Reduction Brake Band | 2002-On |
| BUSHINGS | | | | |
| --- | K93980 | 1 | Bushing Assortment Kit | 2002-On |
| 43C | 65010 | 1 | Pump Bushing | 2002-On |
| THRUST WASHERS AND BEARINGS | | | | |
| --- | K93941 | 1 | Thrust Bearing Kit | 2002-On |
| TRANSMISSION OIL FILTERS | | | | |
| 50B | 93600 ² | 1 | Oil Filter (Disassembly Required) Mazda, Jaguar, Freelander | 2002-On |
| 50B | 93600B ² | 1 | Oil Filter (Disassembly Required) Volkswagen | 2002-06 |
| 50B | 93600C ² | 1 | Oil Filter (Disassembly Required) Rover 75 | 2002-On |
| ² Please See Filter Pictures on Page 6.9-2 for Visual Identification. | | | | |
| MOLDED RUBBER PISTONS | | | | |
| 68E | 93847 | 1 | High Clutch Retainer (Molded Rubber) | 2002-On |
| SPRAGS AND ROLLER CLUTCHES | | | | |
| 70A | 93814 | 1 | Reduction Clutch Sprag | 2002-On |
| 71B | 93813 | 1 | Low Roller Clutch | 2002-On |

Jatco JF506E

JATCO JF506E / 5F31J / JA5A-EL (FWD 5-Speed)

| ILL. NO. | PART NUMBER | PER CAR | DESCRIPTION | YEARS |
|--|----------------|------------|--|---------|
| SHIFT ENHANCEMENTS AND VALVES | | | | |
| --- | K93887 | 1 | TCC Control Plunger Valve Assembly (Sonnax) Addresses: Excessive TCC Slip, Converter Codes, Converter Overheat and Cooler Circuit Oil Loss. | 2002-On |
| --- | K93987 | 1 | TCC Regulator Valve and Sleeve Kit (Sonnax, Oversized)..... Addresses: Converter-Related Codes and Complaints, Damaged TCC Lining and Lube Failures. Use w/K93587 Reamer Kit. | 2002-On |
| --- | K93989 | 1 | Pressure Regulator Valve Kit (Sonnax, Oversized) Addresses: Erratic Line Pressure, Delayed Engagements, Loss of Lockup, Low Line in Drive Range and High Pressure In Reverse. Use w/K93589 Reamer Kit. | 2002-On |
| --- | K93884 | 1 | TCC Control Valve and Plunger Assembly (Sonnax) This Assembly has been Modified to Create a Shorter and Firmer TCC Apply than the OEM Version. Prevents Premature, Shuttle or Loss of Lockup and Overheating. | 2002-On |
| ELECTRONIC COMPONENTS | | | | |
| Mazda: | | | | |
| --- | K93879A | 1 | Solenoid Kit | 2002-06 |
| 80D | 93871 | 1 | Shift Solenoid "A" | 2002-06 |
| 81D | 93871A | 1 | Shift Solenoid "B" | 2002-06 |
| 82D | 93871B | 1 | Shift Solenoid "C" | 2002-06 |
| 83D | 93872 | 1 | Reduction Timing Solenoid | 2002-06 |
| 84D | 93879 | 1 | Line Pressure Control Solenoid | 2002-06 |
| 85D | 93874 | 1 | 2-4 Brake Duty Solenoid | 2002-06 |
| 86D | 93870 | 1 | T.C.C. Solenoid | 2002-06 |
| 87D | 93874 | 1 | High Clutch Timing Solenoid | 2002-06 |
| 88D | 93872A | 1 | Neutral Shift Solenoid | 2002-06 |
| 89D | K93869 | 1 | Internal Wiring Harnesses w/TOT | 2002-06 |
| --- | 93875 | 1 | Turbine Speed Sensor (Internal) | 2002-06 |
| --- | 93875 | 1 | Intermediate Speed Sensor (Internal) | 2002-06 |
| --- | 93875 | 1 | Output Speed Sensor (Internal) | 2002-06 |
| Volkswagen, Jaguar, Freelander & Rover: | | | | |
| --- | K93879B | 1 | Solenoid Kit | 2002-On |
| 80D | 93871J | 1 | Shift Solenoid "A" | 2002-On |
| 81D | 93871A | 1 | Shift Solenoid "B" | 2002-On |
| 82D | 93871BJ | 1 | Shift Solenoid "C" | 2002-On |
| 83D | 93872J | 1 | Reduction Timing Solenoid | 2002-On |
| 84D | 93879 | 1 | Line Pressure Control Solenoid | 2002-On |
| 85D | 93874B | 1 | 2-4 Brake Duty Solenoid | 2002-On |
| 86D | 93870B | 1 | T.C.C. Solenoid | 2002-On |
| 87D | 93873B | 1 | Low Clutch Timing Solenoid | 2002-On |
| 88D | 93872B | 1 | 2-4 Brake Timing Solenoid | 2002-On |
| 89D | K93869B | 1 | Internal Wiring Harnesses w/TOT | 2002-On |
| --- | 93875 | 1 | Turbine Speed Sensor (Internal) w/2-Pin Connector | 2002-On |
| --- | 93875B | 1 | Turbine Speed Sensor (Internal) w/3-Pin Connector | 2002-On |
| --- | 93875 | 1 | Intermediate Speed Sensor (Internal) | 2002-On |
| --- | 93875 | 1 | Output Speed Sensor (Internal) | 2002-On |

JATCO JF506E / 5F31J / JA5A-EL (FWD 5-Speed)

| ILL. NO. | PART NUMBER | PER CAR | DESCRIPTION | YEARS |
|---|----------------|------------|--|---------|
| HARD PARTS AND MISCELLANEOUS | | | | |
| Note : When ordering Hard Parts, please add the appropriate suffix : (-R) Reman, (-U) Used, (-A) Aftermarket. | | | | |
| 120C | K93895 | 1 | Front Pump Assembly | 2002-On |
| 140D | 93285 | 1 | Reverse Clutch Snap Ring (Large) | 2002-On |
| 145E | 93840 | 1 | Reverse Piston (Aluminum Updated Design, Commonly Broken) | 2002-On |
| 150D | 95-110A | 1 | Reman Valve Body Volkswagen, Jaguar, Rover & Freelander | 2002-On |
| 150D | 30-112 | 1 | Reman Valve Body Mazda MPV | 2002-06 |
| 150D | 30-112A | 1 | Reman Valve Body Mazda 6 | 2003-05 |
| Notes: | | | | |

Jatco JF506E