

Vehicle information

2014 Land Rover Discovery

VIN: SALLAAAG5EA709883

Mileage:

Diagnostic time: 2023-09-17 12:08:32

Diagnostic path: Diagnosis\Auto scan\

Status report

System name	DTC counts	Status
PCM - Powertrain control module	0	Pass
TCM - Transmission control module	0	Pass
ABS - ABS control module	0	Pass
RCM - Restraints control module	0	Pass
IPC - Instrument cluster control module	4	Fault
PBM - Parking brake control module	0	Pass
BCM - Body control module	1	Fault
ATCM - All terrain control module	0	Pass
GSM - Gear shift module	0	Pass
GWM - Gateway module	0	Pass
PAM - Parking assist control module	0	Pass
RLM - Ride level control module	0	Pass
TCCM - Transfer case control module	0	Pass
VIM - Vehicle immobilizer control module	1	Fault
AHCM - Auxiliary heater control module	0	Pass
DDM - Driver's door module	0	Pass
FCDIM - Front control/display interface module (high level display front)	0	Pass
FCIM - Front controls interface module (heating ventilation air conditioning controls)	2	Fault

FCIMB - Front controls interface module B (front audio control panel)	0	Pass
HVAC - Heating ventilation and air conditioning control module	0	Pass
PDM - Passenger's door module	0	Pass
RFA - Keyless vehicle module	0	Pass
AAM - Audio amplifier module	0	Pass
ACM - Audio front control module	0	Pass
DABM - Digital audio broadcast module	0	Pass

1. IPC - Instrument cluster control module---(4)

1.1 U0140-00	Lost communication with body control module.	Intermittent
1.2 U0164-00	Lost communication with heating ventilation and air conditioning control module.	Intermittent
1.3 U0184-00	Lost communication with audio unit.	Intermittent
1.4 U0214-00	Lost communication with the remote function actuation.	Intermittent

2. BCM - Body control module---(1)

2.1 U201B-54	Control module calibration data 2.	Permanent
--------------	------------------------------------	-----------

3. VIM - Vehicle immobilizer control module---(1)

3.1 U0001-88	High speed CAN communication bus	Intermittent
--------------	----------------------------------	--------------

4. FCIM - Front controls interface module (heating ventilation air conditioning controls)---(2)

4.1 U0164-00	Lost communication with heating ventilation and air conditioning control module.	Intermittent
4.2 U0424-68	Invalid data received from heating, ventilation and air conditioning control module.	Intermittent