

Vehicle information

2014 Land Rover Discovery 3\4 (L319)

VIN: SALLAAAG5EA709883

Mileage:

Diagnostic time: 2023-09-17 14:38:50

Diagnostic path: Automatic selection\Diagnosis\Auto scan\

Status report

System name	DTC counts	Status
TCM - Transmission control module	5	Fault
ABS - ABS control module	4	Fault
RCM - Restraints control module	4	Fault
IPC - Instrument cluster control module	15	Fault
PBM - Parking brake control module	6	Fault
BCM - Body control module	7	Fault
ATCM - All terrain control module	4	Fault
GSM - Gear shift module	3	Fault
GWM - Gateway module	1	Fault
PAM - Parking assist control module	3	Fault
RLM - Ride level control module	5	Fault
SASM - Steering angle sensor module	1	Fault
TCCM - Transfer case control module	5	Fault
AHCM - Auxiliary heater control module	0	Pass
DDM - Driver's door module	0	Pass
FCDIM - Front control/display interface module (high level display front)	0	Pass
FCIM - Front controls interface module (heating ventilation air conditioning controls)	2	Fault
FCIMB - Front controls interface module B (front audio control panel)	0	Pass

HVAC - Heating ventilation and air conditioning control module	0	Pass
PDM - Passenger's door module	0	Pass
RFA - Keyless vehicle module	0	Pass
AAM - Audio amplifier module	0	Pass
ACM - Audio front control module	0	Pass
DABM - Digital audio broadcast module	0	Pass

1. TCM - Transmission control module---(5)

1.1 U0001-88	High speed CAN communication bus	Intermittent
1.2 U0121-63	Lost communication with ABS control module	Temporary
1.3 U0138-63	Lost communication with all terrain control module	Permanent
1.4 U0126-63	Lost communication with steering angle sensor module	Permanent
1.5 P279D-02	Four wheel drive range signal circuit	Intermittent

2. ABS - ABS control module---(4)

2.1 U0001-88	High speed CAN communication bus	Permanent
2.2 U0101-00	Lost communication with transmission control module	Permanent
2.3 U0102-00	Lost communication with transfer case control module	Permanent
2.4 U0126-00	Lost communication with steering angle sensor module	Permanent

3. RCM - Restraints control module---(4)

3.1 U0073-88	Control module communication bus off.	Intermittent
3.2 U0122-87	Lost communication with vehicle dynamics control module.	Permanent
3.3 U0155-87	Lost communication with instrument cluster control module.	Permanent
3.4 B00D2-87	Restraint system malfunction indicator 1	Permanent

4. IPC - Instrument cluster control module---(15)

4.1 U0001-88	High speed CAN communication bus	Intermittent
--------------	----------------------------------	--------------

4.2 U0100-00	Lost communication with engine control module/ powertrain control module 'A'	Intermittent
4.3 U0101-00	Lost communication with transmission control module	Intermittent
4.4 U0102-00	Lost communication with transfer case control module	Intermittent
4.5 U0121-00	Lost communication with ABS control module	Intermittent
4.6 U0126-00	Lost communication with steering angle sensor module	Intermittent
4.7 U0128-00	Lost communication with parking brake control module	Intermittent
4.8 U0132-00	Lost communication with suspension control module A	Intermittent
4.9 U0138-00	Lost communication with all terrain control module	Intermittent
4.10 U0140-00	Lost communication with body control module.	Intermittent
4.11 U0141-00	Lost communication with the body control module A	Intermittent
4.12 U0151-00	Lost communication with restraints control module.	Intermittent
4.13 U0164-00	Lost communication with heating ventilation and air conditioning control module.	Intermittent
4.14 U0184-00	Lost communication with audio unit.	Intermittent
4.15 U0214-00	Lost communication with the remote function actuation.	Intermittent

## 5. PBM - Parking brake control module---(6)

5.1 U0101-00	Lost communication with transmission control module	Permanent
5.2 U0102-00	Lost communication with transfer case control module	Permanent
5.3 U0140-00	Lost communication with body control module.	Permanent
5.4 U0100-00	Lost communication with engine control module/ powertrain control module 'A'	Permanent
5.5 U0121-00	Lost communication with ABS control module	Permanent
5.6 U0073-88	Control module communication bus off.	Permanent

## 6. BCM - Body control module---(7)

6.1 U0121-00	Lost communication with ABS control module	Intermittent
6.2 U0128-00	Lost communication with parking brake control module	Intermittent
6.3 U0100-00	Lost communication with engine control module/ powertrain control module 'A'	Intermittent

6.4 U0102-00	Lost communication with transfer case control module	Intermittent
6.5 U0101-00	Lost communication with transmission control module	Intermittent
6.6 U201B-54	Control module calibration data 2.	Permanent
6.7 U0001-88	High speed CAN communication bus	Intermittent

7. ATCM - All terrain control module---(4)

7.1 U0121-00	Lost communication with ABS control module	Intermittent
7.2 U0101-00	Lost communication with transmission control module	Intermittent
7.3 U0102-00	Lost communication with transfer case control module	Intermittent
7.4 U0001-88	High speed CAN communication bus	Intermittent

8. GSM - Gear shift module---(3)

8.1 U0001-88	High speed CAN communication bus	Intermittent
8.2 U0101-00	Lost communication with transmission control module	Intermittent
8.3 U0140-00	Lost communication with body control module.	Intermittent

9. GWM - Gateway module---(1)

9.1 U0001-88	High speed CAN communication bus	Intermittent
--------------	----------------------------------	--------------

10. PAM - Parking assist control module---(3)

10.1 U0001-81	High speed CAN communication bus	Intermittent
10.2 U0001-87	High speed CAN communication bus	Intermittent
10.3 U0001-88	High speed CAN communication bus	Intermittent

11. RLM - Ride level control module---(5)

11.1 U0122-00	Lost communication with vehicle dynamics control module.	Intermittent
11.2 U0416-68	Invalid data received from vehicle dynamics control module.	Temporary
11.3 U0101-00	Lost communication with transmission control module	Intermittent
11.4 U0102-00	Lost communication with transfer case control module	Intermittent

11.5 U0073-88	Control module communication bus off.	Permanent
---------------	---------------------------------------	-----------

12. SASM - Steering angle sensor module---(1)

12.1 U0001-88	High speed CAN communication bus	Intermittent
---------------	----------------------------------	--------------

13. TCCM - Transfer case control module---(5)

13.1 U0001-88	High speed CAN communication bus	Intermittent
13.2 U0121-00	Lost communication with ABS control module	Intermittent
13.3 U0126-00	Lost communication with steering angle sensor module	Intermittent
13.4 U0132-00	Lost communication with ride level control module.	Intermittent
13.5 U0138-00	Lost communication with all terrain control module	Intermittent

14. FCIM - Front controls interface module (heating ventilation air conditioning controls)---(2)

14.1 U0164-00	Lost communication with heating ventilation and air conditioning control module.	Intermittent
14.2 U0424-68	Invalid data received from heating, ventilation and air conditioning control module.	Intermittent