


[Click here to print](#)

Connector: **C0071**



Part No.: **YPCI0426**

Colour: **NATURAL**


Cavities: **3WY**

Harness: **WING LH HARNESS**

Description: **Motor-Headlamp-levelling-LH**

Location: **Behind LH headlamp**

Qualifier:



Wire Chart

CAV	TERMINAL	CSA	COL	CCT	DESTN
1	YPLI0073	0.5D	UY	I07	CI265
2	YPLI0073	0.5D	B	I07	CTAP
3	YPLI0073	0.5D	RO	I07	CI265

Service Repair Kits

Refer to Harness Repair information

Se référer aux informations de réparation de faisceau

Siehe Informationen über Kabelbaumreparaturen

Vedere le informazioni che trattano le operazioni


di riparazione del cablaggio

Remítase a la información sobre reparación de

mazos de cables

Raadpleeg de informatie over kabelboomreparaties

Connector: **C0071**



Part No.: **YPCI0426**

Colour: **NATURAL**


Cavities: **3WY**

Harness: **WING LH HARNESS**

Description: **Motor-Headlamp-levelling-LH**

Location: **Behind LH headlamp**

Qualifier:



Wire Chart

CAV	TERMINAL	CSA	COL	CCT	DESTN
1	YPLI0073	0.5D	UY	I07	CI265
2	YPLI0073	0.5D	B	I07	CTAP

Service Repair Kits

Refer to Harness Repair information

Se référer aux informations de réparation de faisceau

Siehe Informationen über Kabelbaumreparaturen