

[Click here to print](#)

Connector: **C1547**

**CONNECTOR HOUSING NOT SERVICEABLE**

**Access Denied**

Engineering Part Number: **9HC2-14463-GXA**

Service Part Number:

Colour: **TIN PLATED**

Cavities: **1WY**

Harness: **EARTH CHASSIS/BIW HARNESS**

Wire Chart

Cav	CSA	Col	Cct	Destn
1	35.0	B	499	C0822

Connector: **C1547**

**CONNECTOR HOUSING NOT SERVICEABLE**

**Access Denied**

Engineering Part Number: **9HC2-14463-GXA**

Service Part Number:

Colour: **TIN PLATED**

Cavities: **1WY**


Harness: **EARTH CHASSIS/BIW HARNESS**

Wire Chart

Description: **Ground**

Location: **Lower RH front of engine compartment**


Qualifier:



Description: **Ground**

Location: **Lower RH front of engine compartment**

Qualifier:



<b>Cav</b>	<b>CSA</b>	<b>Col</b>	<b>Cct</b>	<b>Destn</b>
1	35.0	B	499	C0822