


[Click here to print](#)

Connector: **C0557**



Part No.: **YPG900110**

Colour: **TIN PLATED**


Cavities: **IWY**

Harness: **CHASSIS HARNESS**

Description: **Ground point**

Location: **RH side of transfer box**

Qualifier:



Wire Chart

CAV	TERMINAL	CSA	COL	CCT	DESTN
I	-	4.0D	B	770	S/JJOINT SJ2

Service Repair Kits

Refer to Harness Repair information

Se référer aux informations de réparation de faisceau


Siehe Informationen über Kabelbaumreparaturen

Vedere le informazioni che trattano le operazioni
di riparazione del cablaggio

Remítase a la información sobre reparación de
mazos de cables

Raadpleeg de informatie over kabelboomreparaties

Connector: **C0557**



Part No.: **YPG900110**

Colour: **TIN PLATED**


Cavities: **IWY**

Harness: **CHASSIS HARNESS**

Description: **Ground point**

Location: **RH side of transfer box**

Qualifier:



Wire Chart

CAV	TERMINAL	CSA	COL	CCT	DESTN
I	-	4.0D	B	770	S/JJOINT SJ2

Service Repair Kits

Refer to Harness Repair information

Se référer aux informations de réparation de faisceau

Siehe Informationen über Kabelbaumreparaturen