

[Click here to print](#)

Connector: **C0237**


Description: **Heated seat-LH**

Location: **Beneath front seat**

Qualifier: **RH side illustrated LH side similar**



Harness: **SEAT LINK HARNESS**



Wire Chart

CAV	TERMINAL	CSA	COL	CCT	DESTN
1	YPL101910	0.75D	US	56	C0751
2	YPL101910	0.75D	B	56	C0751

Service Repair Kits

CSA	0.75- 0.75 CSA	
Cavities: 1,2		
418-549-04	SRK ITEM MQS FAMILY 0.75CSA	I
418-112	SRK ITEM	I
418-107	SRK ITEM PIDG RED	I
418-117	SRK ITEM	I
418-116A	SRK ITEM	I
418-616	SRK ITEM MQ FAMILY	I
418-595	SRK ITEM MPQ FAMILY	I
VUB500080		

Connector: **C0237**

Description: **Heated seat-LH**

Location: **Beneath front seat**

Qualifier: **RH side illustrated LH side similar**