



[Click here to print](#)

Connector: **C0361**

Description: **Earth-Radio**

Location: **Behind center of Instrument panel**

Qualifier:



Part No.: **YPG900270**

Colour: **TIN PLATED**

Cavities: **IWY**

Harness: **MAIN LH + RH HARNESS**

Wire Chart

CAV	TERMINAL	CSA	COL	CCT	DESTN
I	-	1.0D	B	499	C0098

Service Repair Kits

Refer to Harness Repair information

Se référer aux informations de réparation de faisceau

Siehe Informationen über Kabelbaumreparaturen

Vedere le informazioni che trattano le operazioni di riparazione del cablaggio

Remítase a la información sobre reparación de mazos de cables



Raadpleeg de informatie over kabelboomreparaties

Connector: **C0361**

Description: **Earth-Radio**

Location: **Behind center of Instrument panel**

Qualifier:



Part No.: **YPG900270**

Colour: **TIN PLATED**

Cavities: **IWY**

Harness: **MAIN LH + RH HARNESS**

Wire Chart

CAV	TERMINAL	CSA	COL	CCT	DESTN
I	-	1.0D	B	499	C0098

Service Repair Kits

Refer to Harness Repair information

Se référer aux informations de réparation de faisceau

Siehe Informationen über Kabelbaumreparaturen