

pscan.uk 0435

Petrol engine

Diesel engine

Transmission

ABS

Airbags

Dash & Service light

Alarm, Immobiliser & Body

Power steering

Climate control

OBD2 / EOBD

EDC 1.3.1

EDC15M

DDE4 / EDC15C4

TD5








Protocol

BMW

Select Log File

Back

Next



11:55

17/02/2022

pscan.uk 0435

+ -	Parameter (Click + to select)	Result
-	Live data update interval	5211ms
-	Engine speed	779 RPM
-	Low pressure supply	414.6 kPa
-	Rail pressure	30 MPa
-	Fuel pressure regulator duty cycle	16.6 %
-	Accelerator pedal 1	0.0 %
-	Accelerator pedal 1 sensor	0.72 V
-	Accelerator pedal 2	0.0 %
-	Accelerator pedal 2 sensor	0.37 V
-	Air mass measured	504.9 mg/s
-	Air mass requested	565.0 mg/s
-	Coolant temperature	64 °C
-	Intake air temperature	14 °C
-	Battery voltage	14.8 V
-	Atmospheric pressure	98 kPa
-	Inlet manifold pressure measured	98 kPa
-	Inlet manifold pressure requested	98 kPa
-	Sensor supply voltage 1	5.01 V
-	Sensor supply voltage 2	5.01 V
-	Regulator current	0.71 A
-	Vehicle speed	0 kph
-	Capacitor voltage bank 1	78.7 V
-	Injection quantity pre-injection	1.19 mm³/s
-	Injection quantity main-injection	8.59 mm³/s
-	EGR circuit duty cycle	5.0 %
-	Exhaust flap duty cycle	16.6 %
-	Brake pedal switch 1	Not pressed
-	Brake pedal switch 2	Not pressed
-	Clutch pedal switch	Pressed
-	Auto gearbox gear selected	Park or Neutral

Back \ Text - Text + ☐ Automatic reordering

11:53 17/02/2022

pscan.uk 0435

	Parameter (Click + to select)	Result
-	Live data update interval	546ms
-	Fuelling compensation cyl 1	0.4 mm³
-	Fuelling compensation cyl 2	-0.2 mm³
-	Fuelling compensation cyl 3	-0.8 mm³
-	Fuelling compensation cyl 4	0.1 mm³








Back


\

Text -

Text +


☐ Automatic reordering





11:54  
17/02/2022






pscan.uk 0435

+ -	Parameter (Click + to select)	Result
-	Live data update interval	1591ms
-	Driving mode	Normal
-	Gear selector	N
-	Current gear	P/N
-	Coolant temperature	106.31 °C
-	Output speed	0 rpm
-	Engine speed	781 rpm
-	Indexed torque	6 %
-	Torque override	6 %
-	Line pressure duty ratio	98 %
-	Lockup pressure duty ratio	4 %
-	2/4 brake pressure duty ratio	98 %
-	Accelerator pedal	0 %
-	Brake pedal switch	Off
-	Shift down switch	Off
-	Shift up switch	Off
-	Sport switch	Off
-	Cruise input	Off
-	Ignition input	On
-	Transmission fluid overtemp	Off
-	Brake solenoid	Off
-	Reduction solenoid	Off
-	Low clutch solenoid	Off
-	A shift solenoid	On
-	C shift solenoid	On
-	B shift solenoid	On
-	Input speed	760 rpm
-	Inter speed	0 rpm
-	Transmission fluid temperature	38.89 °C

Back - Text - Text + ☒ Automatic reordering

12:07 17/02/2022



+ -	Parameter (Click + to select)	Result
-	Live data update interval	1514ms
-	Front wiper state	Released
-	Key sense (year 2000>)	Key out
-	Immobiliser input (year 2000>)	Idle
-	Immobiliser state (year 97-99)	Immobilised
-	EKA manager state (year 97-99)	Entry mode
-	EKA entry state (year 97-99)	Waiting
-	Locking state	Unlocked
-	Arming state	Disarmed
-	Volumetric state	Idle
-	Alarm activation	No trigger
-	Inertia switch	Not tripped
-	Vehicle speed	0 kph
-	Oil pressure sense	Open
-	Drivers door switch	Closed
-	Passenger door switch	Closed
-	Bonnet switch	Closed
-	Tailgate switch	Closed
-	Roof sense	On
-	Centre console lock button	Not pressed
-	Centre console unlock button	Not pressed
-	Key lock	Idle
-	Key unlock	Idle
-	Tailgate open request	Idle
-	Courtesy lamp	Off
-	Tailgate window control state	Stationary
-	Tailgate window monitor	Off
-	Tailgate window up request	Idle
-	Tailgate window down request	Idle
-	Tailgate window position	0
-	Ignition switch	On

Back

-

Text -

Text +

☒ Automatic reordering




+ -	Parameter (Click + to select)	Result
-	Drivers door switch	Closed
-	Passenger door switch	Closed
-	Bonnet switch	Closed
-	Tailgate switch	Closed
-	Roof sense	On
-	Centre console lock button	Not pressed
-	Centre console unlock button	Not pressed
-	Key lock	Idle
-	Key unlock	Idle
-	Tailgate open request	Idle
-	Courtesy lamp	Off
-	Tailgate window control state	Stationary
-	Tailgate window monitor	Off
-	Tailgate window up request	Idle
-	Tailgate window down request	Idle
-	Tailgate window position	0
-	Ignition switch	On
-	Rear fog lamp button	Not pressed
-	Headlights	Off
-	Side lamps (year 2000>)	Off
-	Tailgate window heater button	Not pressed
-	Tailgate wiper request	Off
-	Tail wash sense	Off
-	Tail wiper park	Parked
-	Intermittent speed	2
-	Reverse gear sense	Forward
-	Front wiper park	Parked
-	Front wash sense	Off
-	Front wiper intermittent	Off
-	Tailgate wiper state	Off screen


Back

Text -

Text +

☒ Automatic reordering





pscan.uk 0435

+ -	Parameter (Click + to select)	Result
-	Live data update interval	265ms
-	Engine immobilisation	Mobilised
-	Key transponder chip presence	Present
-	Key transponder number	1
-	Starter motor	Enabled
-	Ignition input	On
-	Instrument pack ignition	On
-	Double locked	No
-	Engine speed	800 RPM








Back


\

Text -

Text +

☒ Automatic reordering





12:13  
17/02/2022

